INVOICE 02/16/98 10:37:51

ORD # 98-02-272 INVOICE # 971838

INVOICE Milbank Manufacturing Company	REMIT See Below TERMS Net 30 Days
TO 1400 E. Havens	то
P.O. Box 754	
Kokomo, IN 46903-0754	
ATTEN Ronda S. Yeakley	ATTEN Accounts Receivable
	PHONE (317) 290-1471
WORK ID Effluent Water Composite	
P.O. # 207777	Thank you for your business. We look forward to working with
	you again in the future.
REPORT Milbank Manufacturing Company	
TO 1400 E. Havens	
P.O. Box 754	
Kokomo, IN 46903-0754	
ATTEN Ronda S. Yeakley	
RECEIVED 02/11/98 CLIENT MILBANK MFG	
REPORTED 02/13/98 PROJECT	
<u>ID</u> <u>CODE</u> <u>DESCRIPTION</u>	REMARK PRICE QTY DISCOUNT AMOUNT

TESTS AG_IC Silver, ICAPES FE_IC Iron, ICAPES PB_IC Lead, ICAPES ZN_IC Zinc, ICAPES QUOTED PRICE \$147.00 TOTAL INVOICE AMOUNT

CERTIFICATE OF ANALYSIS

Milbank Manufacturing Company

1400 E. Havens P.O. Box 754

Kokomo, IN 46903-0754 Attn: Ronda S. Yeakley

Purchase Order: 206941

Invoice Number:

Order #: 98-02-272

Date: 02/13/98 11:44

Work ID: Effluent Water Composite

Date Received: 02/11/98
Date Completed: 02/12/98

Client Code: MILBANK_MFG

SAMPLE IDENTIFICATION

Sample

Sample

Number Description

Effluent Water Composite

Sample Number Sample

Description

This report may not be reproduced except in full, without the written approval of the laboratory. All results relate only

to the items tested.

This report contains a total number of pages: 02

Certified By

A Member of THE ASTBURY GROUP





Order # 98-02-272 02/13/98 11:44


TEST RESULTS BY SAMPLE

Page 2

Sample: 01AW Effluent Water Composite Collected: 02/10/98 Category: WATER

Test Description	Result	<u>Limit</u>	Units	Analyzed	By
Iron, ICAPES	0.551	0.010		02/12/98	
Lead, ICAPES	<0.040	0.040	mg/L	02/12/98	JAR
Silver, ICAPES	<0.010	0.010	mg/L	02/12/98	JAR
Zinc, ICAPES	8.420	0.010	mg/L	02/12/98	JAR







ESG L ratories

5933 West 71" Street * Indianapolis, 1N 46278 Phone (317) 290-1471 * Fax (317) 290-1670

CHAIN OF CUSTODY RECORD

					1000000			1			,	,	,	,	,	,	,	,
Client N	lame:	אחו	2		ESG Work Orde	r #:) <u>) </u>		1	d (Y or v. Code	/-	/-	_/		/-	-/-	$-\!\!\!/$	_/_/_/	Preservation
Project			Project	Name:		Ar Ager H		reser	r. Cone		/	/-/	/	/	/	/-/	/_/_/	Codes:
l							Total	Analy	ses	25/								A = Acid
Sample	r(s) Şignatı	re:		7 /	•		Number		ses 1		/ ,	/ ,		/ ,	/ ,	/ ,	/ /	B = Base
	Lint	5	In	n			of	/	162									C = Cool 4°
Stat.No	DATE	TIME		GRAB	STATION LOC		Containers	1	<u>X</u> _	\leftarrow	\leftarrow	\leftarrow	_	\leftarrow	\leftarrow	\leftarrow	Comments	
	2-10-98	700-300	X		Eff/vent	PIT		X							-		:	
										ļ	ļ							
														·				
						,												
													-					
	,	·																
																	-	
													1.					
														3 3				
					· A A													
Relinqu	ished By:		Date /		Received Ly:	<i>((</i>	ate / Time											
	100	$\gamma//$	0 '	10/12	Kle	411/18	100		Turn	Arour	ıd Tin	ie: No	rmal		Rush		Report Due:	
Kul	TE C	W.	241-9	8														
Relinquished By: Date / Time Received By: Da			ate / Time	Are samples suspected to be: Flammable Corrosive Toxic								Toxic						
									Were	sampl	es rec	eived i	intact	and p	roper	ly pre	served? Yes	No L
Relinqu	ished By:	,	Date /	Time	Received By:	D	ate / Time											
									Temp	. Blan	k	°C						
										<u> </u>								